HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

HAER MONT 27-TROY, Y

Troy-Libby Highway Troy vicinity Lincoln County Montana HAER No. MT-66

NOTE: Photographs were taken by Travis Smith, photographer, June 1989. All 8x10 images were enlarged from 4x5 negatives.	
MT-66-I	VIEW OF ROAD (SECTION G) WITH ROCK CUT AT RIGHT, LOOKING EAST
MT-66-2	VIEW OF ROCK RETAINING WALL WHERE STEEL POST GUARDRAIL ONCE STOOD (SECTION G), LOOKING SOUTHEAST
MT-66-3	VIEW OF ROCK RETAINING WALL AT TOP OF STEEL TALUS SLOPE (SECTION G), LOOKING SOUTHWEST
MT-66-4	CLOSE-UP VIEW OF ROCK RETAINING WALL (SECTION G), SHOWING HOW ROCK OUTCROPS WERE INCORPORATED IN THE WALL, LOOKING SOUTHWEST
MT-66-5	CLOSE-UP VIEW OF ROCK RETAINING WALL OPPOSITE STEEP ROCK CUT (SECTION G), LOOKING SOUTHWEST
MT-66-6	VIEW OF ROCK RETAINING WALL AND ROCK OUTCROP (SECTION E), LOOKING EAST
MT-66-7	CLOSER VIEW OF ROCK RETAINING WALL (SECTION E), LOOKING EAST FROM BELOW
MT-66-8	VIEW OF ROAD GOING AROUND ROCK OUTCROP (SECTION E), LOOKING EAST
MT-66-9	VIEW OF ROCK CAUSEWAY (SECTION E), LOOKING NORTHEAST
MT-66-10	SCENIC VIEW OF KOOTENAI RIVER VALLEY FROM ROAD (SECTION E), LOOKING NORTHWEST
MT-66-11	VIEW OF ROAD ACROSS RELATIVELY FLAT TERRAIN, IN THE SHADOW OF TALL TREES (SECTION 3)

Troy-Libby Highway HAER No. MT-66 Index to Photographs (Page 2)

MT-66-12	VIEW OF ROAD ACROSS RELATIVELY FLAT TERRAIN (SECTION E), RECENTLY CLEARED OF SMALL TREES AND BRUSH BY THE KOOTENAI NATIONAL FOREST
MT-66-13	VIEW OF ROAD IN THE SHADOW OF TOWERING TREES (SECTION E)
MT-66-14	VIEW OF REMNANTS OF A LOG BRIDGE ABUTMENT ACROSS AN UNNAMED GULLEY (SECTION E), LOOKING EAST
MT-66-15	VIEW OF REMNANTS OF A LOG BRIDGE, WITH THE ROAD AND CUT BANK IN THE BACKGROUND (SECTION E), LOOKING SOUTHWEST